


# Component List of 3S Air Pin Type Lower Electrode Set for M12

## Model No. list

| Model No.                   |                               | ① 3S Air Pin<br>For Nut Welding | ② Air Cap<br>For Nut Welding | ③ Lower Holder<br>For Nut Welding |
|-----------------------------|-------------------------------|---------------------------------|------------------------------|-----------------------------------|
| Square Nut<br>Hexagonal Nut | <b>PNSET-12-12.8-3016-1-K</b> | DPN-12P-12.8-K                  | PN-C127-13.0-30-C            | PN-SH2-1 (T=1/10)                 |
|                             | <b>PNSET-12-12.8-3016-2-K</b> |                                 |                              | PN-SH2-2 (T=MT#2)                 |
|                             | <b>PNSET-12-12.8-3016-3-K</b> |                                 |                              | PN-SH2-3 (T=1/5)                  |



[ Applicable conditions ]

**Square Nut / Hexagonal Nut**



Workpiece thickness: ~t2.6  
Pilot hole: φ13.0

| Part name                                                                    | Use Quantity | MOQ  |
|------------------------------------------------------------------------------|--------------|------|
| 3S Air Pin Type Lower Electrode Set                                          | -            | 1set |
| ① 3S Air Pin For Nut Welding Center-Misalignment Prevention, Shouldered Type | 1            | 1    |
| ② Air Cap For Nut Welding                                                    | 1            | 1    |
| ③ Air & Spring Lower Holder for Nut Welding                                  | 1            | 1    |
| <b>Commonn component:</b> Speed Controller B (meter-in)                      | 1            | 1    |
| <b>Commonn component:</b> Bakelite Plate                                     | 1            | 5    |
| <b>Commonn component:</b> Spring                                             | 1            | 5    |